



C. E. Niehoff & Co.
BRUSHLESS ALTERNATORS

Service Bulletin

Field Inspection

Issue Date: January 22, 2001

SB Number: SB0004A

Product: C510 Alternator

Inspection: All vehicles equipped with C510 alternators should be inspected for possible corrosion on regulator harness connector terminals.

Action: **If NO corrosion is found:**

1. Seal any open connector wire cavities with non-corrosive (non-acidic) Silicone/RTV sealant.
2. Allow sealant to cure and re-install connector.
3. Check charging system operation.

If corrosion found:

1. Replace components as needed. Contact CEN to obtain replacement components.
2. Check charging system operation.

Please file this CEN Service Bulletin with your CEN Literature.

Please forward a copy of this information to the appropriate people in your company.