



**C.E. Niehoff & Co.**  
**BRUSHLESS ALTERNATORS**

**A5-338 Anti-Drive End Housing  
with 4-Point or 6-Point Fan Guard  
on C706 Alternator**

Replacement Notice

**A5-338 anti-drive end housing  
requires a 6-Point Fan Guard,  
CEN part number A6-160.**

**If you are replacing this housing on a C706 alternator that has a 4-Point Fan Guard, you will need to order and install a 6-Point Fan Guard to fit on the new housing.**