

## Technical Bulletin Product Information

Issue Date: April 6, 2001 TB Number: TB0001A

Product: All CEN Alternators

The field has reported incidences of improper wiring in emergency vehicle safety circuits. Accepted industry practices prohibit the routing of charging system components to or through safety circuit wiring in any vehicle.

CEN recommends connecting our alternators to an *independent*, fused and switched power source of the vehicle electrical system. The alternator energize circuit must never be connected to or through any vehicle safety system circuit such as ABS, traction control, air bags, brake light, etc. For reasons of safety, never compromise the integrity of vehicle safety systems and wiring.

Please file this CEN Technical Bulletin with your CEN Literature. Please forward a copy of this information to the appropriate people in your company.

C. E. Niehoff & Co. • 2021 Lee Street • Evanston, IL 60202

Tech Services Hotline 800-643-4633